

## ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Darryl M Washington	2. Log Date: 9/25/02	3. CCR #: 02-0848	4. Rev: —	5. Tel: x0734	6. Rm #: 2079	7. Dept. SE
8. CCR Title: Install new microcode on STK 9940A drives						
9. Originator Signature/Date Darryl Washington /s/ 10/2/02			10. Class II	11. Type: CCR	12. Need Date: 10/02/02	
13. Office Manager Signature/Date Carolyn Whitaker /s/ 10/02/02			14. Category of Change: Initial ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): 910-TDA-003			17. Schedule Impact: NONE		18. CI(s) Affected:	
19. Release Affected by this Change: 6A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) STK 9940 drives have been exhibiting "loader" errors (5B41 & 5905) at most of the DAAC sites. STK has initiated a new firmware version to correct these problems. EDC has been particularly plagued by this problem, and has been the "BETA" site for the testing of the new firmware (1.32.208). The new firmware has also been tested in the PVC Prototype LAN. The firmware is now GA (General Availability) for commercial use, and can be installed at all DAACs. This code will eliminate several drive related problems at the DAACs.						
24. Proposed Solution: (use additional sheets if necessary) Install the new microcode for STK 9940 (1.32.208) drives in all DAACs and the VATC.						
25. Alternate Solution: (use additional sheets if necessary)						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) These "loader" errors are intermittent and unpredictable, but will potentially cause significant amounts of downtime when the problem does surface. This microcode resolves this problem.						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 10/2/02			Disposition: <b>Approved</b> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): G. G. Gavigan, Jr. /s/ 10/2/02			Disposition: <b>Approved</b> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

## ADDITIONAL SHEET

**CCR #:** 02-0848    **Rev: — Originator:** Darryl M. Washington

**Telephone:** x0734    **Office:** 2079

**Title of Change:** Install new microcode on STK 9940A drives

STK has developed new microcode (1.32.208) for the 9940A drives to fix "loader" error observed at the DAACs. EDC has been the BETA Test site for the operational testing of these drives. The microcode has also been installed in the Landover EDF (PVC) for testing before it is delivered to the field. The BETA version of the code has been made GA, and can now be installed at the other DAAC locations. This code should be installed on all 9940A drives in the ECS project.

CM01AJA00 Revised 8/2/02

**ECS**